

INSTRUCTIONS

for the use, storage and care of personal protective equipment for hands (protective gloves)

1. General Information

This instruction applies to personal protective equipment (PPE) for hands — protective gloves of various types and materials.

The products comply with the requirements of

EN 420 (DSTU EN 420:2017) — general requirements for protective gloves.

Information on the series, article number, size, date of manufacture, risk category and trade mark is indicated on the product packaging or label.

PPE belongs to risk category (I / II / III) in accordance with Regulation (EU) 2016/425.

2. Intended Use

The gloves are designed to protect hands from mechanical, thermal, chemical or other occupational hazards depending on the product model.

Specific protective properties are defined by the applicable standards indicated on the product.

3. Marking and Standards

The marking on the product includes pictograms and levels of protective properties in accordance with the applicable standards.

The pictograms are accompanied by numerical or alphanumeric values indicating the level of protection.

The interpretation of values is provided in this instruction.

The gloves bear pictograms and markings in accordance with the applicable standards:

- EN 388 — protection against mechanical risks
- EN 511 — protection against cold
- EN ISO 374-1 — protection against chemical substances
- EN 407 — protection against heat and flame

The symbol «X» means that the parameter was not determined or does not apply.

4. Protection Levels (for EN 388)

Protection levels are determined by the following parameters:

- Abrasion resistance (0–4)
- Cut resistance (0–5 or A–F)
- Tear resistance (0–4)
- Puncture resistance (0–4)

The higher the value of the parameter — the higher the level of protection.

5. Pre-Use Instructions

Before use, it is necessary to:

- perform a visual inspection of the product for damage
- check the integrity of the material and coating
- ensure correct size selection

Use of damaged or worn gloves is prohibited.

6. Limitations of Use

Gloves do not provide absolute protection against all risks.

Do not use:

- when working with rotating or moving parts of machinery
- when in contact with substances not covered by the standards
- if the product is damaged

Protective properties may be reduced due to:

- wear
- contamination
- improper care
-

7. Risk Assessment

The selection of gloves must be made taking into account the specific working conditions and the nature of the risks.

The user is responsible for the correct selection of protective equipment.

8. Care and Cleaning

Do not use aggressive chemical solvents.

- Coated gloves (nitrile, latex, PU, PVC): cleaning with mild detergents is permitted
- Leather and combined: clean with a damp cloth, do not immerse in water

After cleaning:

- dry naturally
- do not dry near open heat sources

Machine washing is not permitted unless otherwise stated by the manufacturer.

9. Storage Conditions

Store:

- in a dry, ventilated place
- away from direct sunlight
- recommended storage temperature: from +5°C to +25°C.

10. Service Life

Service life depends on operating conditions, intensity of use and maintenance.

It is recommended to regularly inspect the condition of the gloves and replace them when signs of wear or damage appear, as wear may significantly affect the protective properties.

11. Warnings

- Latex may cause allergic reactions
- In case of skin irritation, discontinue use
- For chemical protection, the compatibility of the material with substances must be verified

12. Manufacturer Information

Manufacturer: LLC "PA "DNIPROSHKIRHALANTEREIA"

Address: 24 Kursantska Street, 49051 Dnipro, Ukraine

Country of manufacture: Ukraine

13. Declaration of Conformity

The EU Declaration of Conformity is available on the manufacturer's official website or provided upon request.